COLORADO 223

HAXTUN MUNI (17V) 2 SE UTC-7(-6DT) N40°37.50′ W102°36.19′

4035 TPA-5035(1000)

RWY 08-26: H3860X40 (ASPH) LIRL (NSTD)

RWY N8. Road RWY 26: Road.

RWY 17-35: 1650X30 (TURF-DIRT)

RWY 17: Building. RWY 35: Road.

AIRPORT REMARKS: Unattended. Rwy 17-35 not maintained, very rough. Rwy 17-35 multiple cracks. Gravel road parallels both rwys


45-55' from centerlines. Rwy 08-26 multiple cracks. Rwy 08-26 NSTD LIRL. No thid lgts. Edge lgts begin 250' of Rwy 08 end. Rwy 08 has +3' pole 3' from left edge 500' from rwy end. Rwy 08 has +3' pole from left edge 500' from rwy end.

COMMUNICATIONS: CTAF 122.9

DENVER FSS (DEN) TF 1-800-WX-BRIEF. NOTAM FILE DEN.

RADIO AIDS TO NAVIGATION: NOTAM FILE SNY.

SIDNEY (H) VORTAC 115.9 SNY Chan 106 N41°05.80' W102°58.98' 135° 33.2 NM to fld. 4300/13E.



HAYDEN N40°31.21′ W107°18.29′ NOTAM FILE DEN.

(H) VORW/DME 115.6 CHE Chan 103 106° 4.6 NM to Yampa Valley. 7230/14E.

RCO 122.25 (DENVER FSS)

CHEYENNE H-3E, L-9E, 11E

CHEYENNE

HAYDEN

YAMPA VALLEY (HDN) 2 SE UTC-7(-6DT) N40°28.87′ W107°13.06′

6602 B FUEL 100LL, JET A OX 3, 4 ARFF Index—See Remarks RWY 10-28: H10000X150 (ASPH-GRVD) S-75, D-170, DT-260

RWY 10: MALSF. PAPI(P4L)-GA 3.0° TCH 55'. Thid dspicd 510'. Rgt tfc

RWY 28: REIL. PAPI(P4L)—GA 3.5° TCH 55', P-line. 0.3% down AIRPORT REMARKS: Attended 1300-0300Z‡. Class I, ARFF Index C from Dec-Mar, ARFF Index B from Apr-Nov, Possible severe winter conditions from Nov-Apr. Check NOTAMS for arpt conditions. No arpt information nor snow removal guaranteed during hours of nonattendance, CLOSED to unscheduled air carrier ops with more than 30 passenger seat except PPR, call arpt manager 970-276-5000. Large flocks of sandhill cranes around arpt in spring. All acft report 10 minutes prior to tkf/ldg on 123.0-monitor frequency 24 hrs, PAEW on rwy. Between 1300-0300Z‡ ctc UNICOM prior to all tkfs and ldgs for PAEW advisories. PPR for escort to-from active rwy during normal business hrs. During snow season ctc UNICOM. Request all acft

departing Rwy 28 make right or left turnout as soon as safety permits after tkf to avoid town of Hayden and comply with noise abatement procedures. Ldg fee for acft 11,000 pounds and over.

ACTIVATE HIRL Rwy 10-28, REIL Rwy 28, PAPI Rwy 10 and MALSF Rwv 10-CTAF.

WEATHER DATA SOURCES: AWOS-3 119.275 (970) 276-3690. COMMUNICATIONS: CTAF/UNICOM 123.0

DENVER FSS (DEN) TF 1-800-WX-BRIEF. NOTAM FILE HDN.

HAYDEN RCO 122.25 (DENVER FSS)

DENVER CENTER APP/DEP CON 120 475

AIRSPACE: CLASS E svc 1400-0400Z‡ other times CLASS G.

RADIO AIDS TO NAVIGATION: NOTAM FILE DEN.

HAYDEN (H) VORW/DME 115.6 CHE Chan 103 N40°31.21′ W107°18.29′ 106° 4.6 NM to fld. 7230/14E. ILS/DME 109.9 I-HDN Chan 36 Rwy 10. Class IB.

CHEYENNE H-3E, L-9E, 11E

IAP

